SERVICE DEPARTMENT BULLETIN

BULLETIN #91205

GENERAL CLASSIFICATION: Control Deck Repair
SPECIFIC SUBJECT: Video Output Resistor (R2) Enhancement

Control Deck PCB Versions 1 through 3 contain a 2.2KΩ Video Output resistor at location R2. In some circumstances, this resistor will cause a loss of color or color wash-out on the video display from the PPU. To correct this, replace the resistor R2 (2.2KΩ) with a 510Ω resistor.

Repair Action

Perform modification and charge customer appropriately. All units affected are beyond the warranty period. No warranty claims will be accepted for this enhancement.